


Conexiones para prensar con camisas pre-prensadas

Macho Fijo Rosca NPT


8201



Nº CODIGO	ROSCA NPT	Ø Interior Maguera
C8201-04-02	1/8 NPT	1/4 SAE100 R1/R2
C8201-04-04	1/4 NPT	1/4 SAE100 R1/R2
C8201-04-04G	1/4 NPT	1/4 SAE100 R1/R2
C8201-06-06	3/8 NPT	3/8 SAE100 R1/R2
C8201-06-06G	3/8 NPT	3/8 SAE100 R1/R2
C8201-06-08G	1/2 NPT	3/8 SAE100 R1/R2
C8201-08-08	1/2 NPT	1/2 SAE100 R1/R2
C8201-08-08G	1/2 NPT	1/2 SAE100 R1/R2
C8201-12-12	3/4 NPT	3/4 SAE100 R1/R2
C8201-12-12G	3/4 NPT	3/4 SAE100 R1/R2
C8201-16-16	1" NPT	1" SAE100 R1/R2
C8201-16-16G	1" NPT	1" SAE100 R1/R2

Hembra giratoria BSP - JIC

8206



Nº CODIGO	ROSCA BSP	Ø Interior Maguera
C8206-04-04	1/4" BSPJIC	1/4" SAE100 R1/R2
C8206-04-06	3/8" BSPJIC	1/4" SAE100 R1/R2
C8206-06-06	3/8" BSPJIC	3/8" SAE100 R1/R2
C8206-06-08	1/2" BSPJIC	3/8" SAE100 R1/R2
C8206-08-08	1/2" BSPJIC	1/2" SAE100 R1/R2
C8206-12-12	3/4" BSPJIC	3/4" SAE100 R1/R2
C8206-16-16	1" BSPJIC	1" SAE100 R1/R2

"Poberaj SA se reserva el derecho de modificar las características y medidas de sus productos sin previo aviso".