


## Conexiones para prensar con camisas pre-prensadas

### Macho Fijo UNF - JIC 37°


**8203**



| Nº CODIGO    | ROSCA UNF | Ø Interior Maguera |
|--------------|-----------|--------------------|
| C8203-04-04  | 7/16"NF   | 1/4" SAE100 R1/R2  |
| C8203-04-05  | 1/2" NF   | 1/4" SAE100 R1/R2  |
| C8203-04-06  | 9/16"NF   | 1/4" SAE100 R1/R2  |
| C8203-06-06  | 9/16"NF   | 3/8" SAE100 R1/R2  |
| C8203-06-06G | 9/16"NF   | 3/8" SAE100 R1/R2  |
| C8203-06-08  | 3/4" NF   | 3/8" SAE100 R1/R2  |
| C8203-08-08  | 3/4" NF   | 1/2" SAE100 R1/R2  |
| C8203-08-08G | 3/4" NF   | 1/2" SAE100 R1/R2  |
| C8203-08-10  | 7/8" NF   | 1/2" SAE100 R1/R2  |
| C8203-10-12G | 1.1/16"NF | 5/8" SAE100 R1/R2  |
| C8203-12-12  | 1.1/16"NF | 3/4" SAE100 R1/R2  |
| C8203-12-12G | 1.1/16"NF | 3/4" SAE100 R1/R2  |
| C8203-16-16  | 1.5/16"NF | 1" SAE100 R1/R2    |
| C8203-16-16G | 1.5/16"NF | 1" SAE100 R1/R2    |

### Macho Fijo UNF para O'Ring

**8204**



| Nº CODIGO   | ROSCA UNF       | Ø Interior Maguera |
|-------------|-----------------|--------------------|
| C8204-12-08 | 3/4"UNF P/ORING | 3/4" SAE100 R1/R2  |

"Poberaj SA se reserva el derecho de modificar las características y medidas de sus productos sin previo aviso".