


## Conexiones para prensar con camisas pre-prensadas

### Hembra Giratoria UNF - JIC 37°


**8205**



Nº CODIGO	ROSCA UNF	∅ Interior Maguera
C8205-04-04	7/16-20 JIC	1/4 SAE100 R1/R2
C8205-04-04G	7/16-20 JIC	1/4 SAE100 R1/R2
C8205-04-05	1/2-20 JIC	1/4 SAE100 R1/R2
C8205-04-06	9/16-18 JIC	1/4 SAE100 R1/R2
C8205-06-06G	9/16-18 JIC	3/8 SAE100 R1/R2
C8205-06-08	3/4-16 JIC	3/8 SAE100 R1/R2
C8205-08-06	9/16 JIC	1/2R2 SAE100 R1/R2
C8205-08-08	3/4-16 JIC	1/2 SAE100 R1/R2
C8205-08-08G	3/4-16 JIC	1/2 SAE100 R1/R2
C8205-08-10	7/8-14 JIC	1/2 SAE100 R1/R2
C8205-08-10G	7/8-14 JIC	1/2 SAE100 R1/R2
C8205-10-12G	1'1/16-12 JIC	5/8 SAE100 R1/R2
C8205-12-12	1'1/16-12 JIC	3/4 SAE100 R1/R2
C8205-12-12G	1'1/16-12 JIC	3/4 SAE100 R1/R2
C8205-12-16G	1 5/16-12 JIC	3/4 SAE100 R1/R2
C8205-16-16	1'5/16-12 JIC	1" SAE100 R1/R2
C8205-16-16G	1'5/16-12 JIC	1" SAE100 R1/R2
C8205-16-20G	1'5/8-12 JIC	1" SAE100 R1/R2
C8205-20-20G	1'5/8 JIC	1'1/4 SAE100 R1/R2

### Macho Fijo UNF asiento virola

**8216**



Nº CODIGO	ROSCA NF-V	∅ Interior Maguera
C8216-04-04	1/4" MF 7/16"NF	1/4" SAE100 R1/R2
C8216-04-05	5/16"MF 1/2" NF	1/4" SAE100 R1/R2
C8216-04-06	3/8" MF 9/16"NF	1/4" SAE100 R1/R2
C8216-06-06	3/8" MF 9/16"NF	3/8" SAE100 R1/R2
C8216-06-08	1/2" MF 3/4" NF	3/8" SAE100 R1/R2
C8216-08-08	1/2" MF 3/4" NF	1/2" SAE100 R1/R2
C8216-08-10	5/8" MF 7/8" NF	1/2" SAE100 R1/R2
C8216-12-12	3/4" MF 1.1/16"NF	3/4" SAE100 R1/R2
C8216-16-16	1" MF 1.5/16"NF	1" SAE100 R1/R2

"Poberaj SA se reserva el derecho de modificar las características y medidas de sus productos sin previo aviso".